

## Contents

<b>Introduction .....</b>	<b>xi</b>
<b>1. Current situation in copper production .....</b>	<b>1</b>
1.1. Copper hydrometallurgy .....	11
<b>2. Ore minerals .....</b>	<b>17</b>
<b>3. Phase equilibrium of copper and iron sulphides .....</b>	<b>29</b>
3.1. One-component systems .....	29
3.1.1. Sulphur .....	29
3.1.1.1. Allotropic modifications of solid sulphur .....	32
3.1.1.2. Phase diagram .....	37
3.2. Multi-component systems .....	38
3.2.1. The copper–sulphur equilibrium phase system .....	38
3.2.2. The iron–sulphur equilibrium phase system .....	43
3.2.3. The copper–iron–sulphur equilibrium phase system .....	48
<b>4. Equilibrium in aqueous solutions .....</b>	<b>60</b>
4.1. Ionic activities .....	65
4.1.1. Debye–Hückel theory .....	65
4.1.1.1. Extension to more concentrated solutions .....	69
4.1.1.2. Extension to mixed electrolytes .....	71
4.1.2. Pitzer method .....	72
4.1.2.1. Calculation of $\phi$ for salts in mixed electrolytes .....	76
4.1.2.2. Calculation of $\gamma$ for salts in mixed electrolytes .....	78
4.1.2.3. Calculation of $\gamma$ for single ions .....	79
4.1.2.4. Studies of complex systems .....	80
4.2. Formation of metallic complexes and equilibrium constant .....	81
4.3. Thermodynamics of equilibrium constants .....	85
4.3.1. Selection of the values of equilibrium constants .....	91
<b>5. Thermodynamic studies of heterogeneous systems in an aqueous medium .....</b>	<b>96</b>
5.1. Theoretical principle of the $E$ –pH diagrams .....	100
5.1.1. pH and its principle .....	102
5.1.2. Potential $E$ and its principle .....	104
5.2. Calculation and construction of $E$ –pH diagrams .....	113
5.2.1. $E$ –pH diagrams at elevated temperatures .....	116

5.3.	Potential–pH diagrams in leaching of copper sulphides .....	127
5.3.1.	S–H <sub>2</sub> O equilibrium system .....	129
5.3.2.	Cu–S–H <sub>2</sub> O equilibrium system .....	145
5.3.3.	Fe–S–H <sub>2</sub> O equilibrium system .....	153
5.3.4.	Cu–Fe–S–H <sub>2</sub> O equilibrium system .....	154
5.3.5.	Cu–S–Cl–H <sub>2</sub> O equilibrium system .....	157
5.3.6.	Fe–S–Cl–H <sub>2</sub> O equilibrium system .....	159
5.3.7.	Equilibrium diagram of the Cu–Fe–S–Cl–H <sub>2</sub> O system .....	163
5.4.	Species diagrams .....	167
<b>6.</b>	<b>Software and databases for thermodynamic calculations</b>	<b>173</b>
<b>7.</b>	<b>Kinetics of heterogeneous reactions of leaching processes .....</b>	<b>184</b>
7.1.	Effect of variables on the kinetics of a heterogeneous reaction .....	190
7.2.	Elementary phenomena at the interface .....	211
7.2.1.	Intrinsic kinetics of heterogeneous reactions on solid surfaces .....	216
7.2.1.1.	Kinetics of processes of leaching a single particle .....	216
7.2.1.2.	Kinetics of leaching processes in multi-particle systems .....	228
<b>8.</b>	<b>Leaching in chloride media .....</b>	<b>242</b>
8.1.	Main aspects of leaching chalcopyrite in a chloride medium .....	243
<b>9.</b>	<b>Extracting metals from solutions .....</b>	<b>255</b>
9.1.	Cementation .....	255
9.2.	Cementation of amalgams .....	259
9.3.	Reduction with gaseous hydrogen .....	261
9.4.	Liquid extraction .....	264
9.5.	Ion exchange .....	268
9.6.	Precipitation of sparingly soluble compounds .....	270
9.7.	Crystallisation .....	274
9.8.	Electrolysis and electrolytic refining .....	276
9.8.1.	Electrowinning of metals .....	278
9.8.2.	Electrolytic refining .....	289
<b>10.</b>	<b>Effect of the electronic structure on leaching of sulphide semiconductors .....</b>	<b>294</b>
10.1.	Leaching kinetics and electrochemistry of sulphides .....	300
10.1.1.	Leaching of chalcopyrite .....	301
<b>11.</b>	<b>Experimental methods of investigating hydrometallurgical processes .....</b>	<b>309</b>
11.1.	Experimental methods of examination of leaching processes .....	315

11.1.1.	Leaching equipment .....	318
11.1.2.	Experimental procedure .....	324
11.2.	Changes of pH in relation to temperature .....	334
<b>12.</b>	<b>Leaching of copper sulphides .....</b>	<b>341</b>
12.1.	Copper sulphides of the $\text{Cu}_x\text{Fe}_y\text{S}_z$ type .....	341
12.1.1.	Leaching of chalcopyrite by ferric sulphate .....	361
12.1.2.	Leaching of chalcopyrite by ferric chloride .....	364
12.1.3.	Leaching of chalcopyrite by ferric chloride with the addition of carbon tetrachloride .....	366
12.1.4.	Leaching of chalcopyrite in sulphuric acid using ozone as the oxidation agent .....	368
12.1.5.	Leaching of chalcopyrite in the high-frequency field .....	375
12.1.6.	Leaching of chalcopyrite in the microwave field .....	378
12.1.7.	Leaching of chalcopyrite in the presence of deep nodules as an oxidation agent .....	384
12.2.	Copper sulphides of the $\text{Cu}_x\text{S}$ type .....	388
12.3.	Copper sulphides of the type $\text{Cu}_x\text{Me}_y\text{S}_z$ .....	398
<b>13.</b>	<b>Morphology and behaviour of sulphur in the leaching of sulphides .....</b>	<b>421</b>
<b>14.</b>	<b>Study of the fine structure .....</b>	<b>444</b>
14.1.	Examples of the application of X-ray diffractometry in hydrometallurgy .....	446
<b>15.</b>	<b>Mechanism of leaching of copper sulphides in an acid medium .....</b>	<b>468</b>
<b>16.</b>	<b>The current state and prospects of hydrometallurgical processes .....</b>	<b>479</b>
16.1.	History of hydrometallurgical processes .....	484
<b>Index .....</b>		<b>535</b>